

RSB Schalungstechnik
Funnels



1.

Uplift protection to tie the funnel-shaped formwork



2.

Reinforcement work, installation of inserts



3.

Reinforcement complete - uplift protection plate assembled



4.

Assembly of the funnel-shaped formwork (supporting steel skeleton)



5.

Funnel-shaped formwork assembled, ready for concrete work






6.

Continuous concrete work, optimum compacting, maximum concrete drop 50 cm



7.

Disassembly of funnel-shaped formwork



8.

Funnel after stripping of formwork